

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



FIG. 1







FIG. 3



A perspective view of a cylindrical container. The container has a central vertical divider and two side dividers. The central divider is labeled 226, and the side dividers are labeled 227 and 228. The container is shown in a perspective view, with the top and bottom edges visible.



FIG. 5

500






FIG. 6






FIG. 7







FIG. 8






FIG. 9(a)




FIG. 9(b)




FIG. 10(a)




FIG. 10(b)






FIG. 11(a)






FIG. 12(b)



FIG. 13




FIG. 14a







FIG. 14b






FIG. 15a





FIG. 15b



FIG. 15c





Inventor: BORZENETS ET AL.
Docket No.: 10467.54US01
Title: RESONATOR TUNING ASSEMBLY AND METHOD
Serial No.: 10/037,292
Sheet 22 of 28




FIG. 16(a)




FIG. 16(b)



FIG. 17






FIG. 18A






FIG. 18b






FIG. 19






FIG. 20

